25X1

(- 3610 (44) Approved For Release 2007/62/04-PCYA-PCYA-PC-4B0049-R 0 0

			SECRET					
FILE INFO			(When	Filled In)		Cer	Utr	
	DECTION 7A		REPRODUC	TION PROHIB	ITED		- 1 00 24	
ACTION	1	MM	6	DIPS	11	16	5	
	2	7	7 7	TOGA	12	17	7	
	3	_ /	8		13	18	3	
	4	15A	9	CMD	14	19)	
	5	RB	1ø		15	20	5	

25X1	S	SECRET		100540Z DEC		71	CITE 3489			
25 ₩ 1	PF	RIC	T							

IDEALIST DM-1/4

REF: Α. В.

- NOISE PARA 3, REF B CAUSED BY HEATER BLANKETS/ CONTROL CIRCUITS OF "H" CONFIG S/N Ø02.
- 2. CONFIG INSTALLED IN ARTICLE 053. (IN THE HANGAR) NOISE WAS SEEN IN RECEIVERS OF SYSTEM 17B L/W, 17B (HEAVY) AND O/S VIDEO. PRESENT WHENEVER "H" IS ON. NOISE DISAPPEARS WHEN HEATERS DIS-CONNECTED, EVEN THOUGH CONFIG STILL ON. NOISE DISAPPEARS WHEN HEATERS RECONNECTED.
- 3. WE ARE CURRENTLY TRYING FOR A FIX. A VALIDATION FLIGHT IS PLANNED FOR MONDAY 13 DEC. WILL ADVISE RESULTS.

SECRET

BT